

NR 1
(B1) $\phi 8 \times 28$ x16
(B22) $\phi 8 \times 35$ x8
(B20) $\phi 8 \times 50$ x2
(M1) $\phi 15 \times 12\text{mm}$ x20
(T1) 5x39mm x16
(T18) L-64 x2
(C2) x20
(G4) x8
(P3) 3,5x18 x8

NR 2
(J23) x22
(F1) x9
(S6) 3,0x20 x9+5
(W1) x16
(W2) x8
(F33) x18
(F18) x2
(P13) 3,5x13 x72+8

NR 3
(Y0) x7
(Z5) x2
(D7) x7
(E3) 6,3x13 x14
(S8) 4x13 x14


NR 4
(J11) x1
(P13) 3,5x13 x2

NR 5
(O20) x2
(O21) x1


NR 6
(N17) x4
(S12) 4x20 x16





1




2




3





4





5




6




7



8



9



10

(S6) 3,0x20 x9+5

(F1) x9

(J23) x22

11










(P13) 3,5x13 x36

12

(O21) x1

(O20) x2

(C2) x20



13

