

NR 1
(B1) $\phi 8 \times 28$ x24
(B22) $\phi 8 \times 35$ x8
(M1) $\phi 15 \times 12mm$ x22
(T1) $5 \times 39mm$ x22
(C2) x16
(J23) x22+4
(S6) $3,0 \times 20$ x14
(F1) x10
(W1) x16
(F33) x17
(P13) $3,5 \times 13$ x68

NR 2
(N17) x4
(S12) 4x20 x16
(N18) x1
(S8) 4x13 x4

NR 3
(R33) L-350mm x2L/2R
(E24) 6,0x11 x8

NR 4
(Y0) x4
(D7) x4
(E3) 6,3x13 x8
(S8) 4x13 x8
(Z5) x2


NR 5
(Y2) $\phi 35$ x2
(D6) H2 x2
(E3) 6,3x13 x4
(S8) 4x13 x4
(Z5) x1

NR 6
(M2) $\phi 12 \times 10mm$ x4
(T2) 5x35mm x4
(P5) 4x30 x8


NR 7
(J44) x1
(P13) 3,5x13 x1
(G22) $\phi 18$ x2




1




2




3




4




5




6




7



8



9







10



S6 3,0x20 x14

F1 x10




J23 x22

**2****3****4****11**


P13 3,5x13 x34



12



13



14

